

Electrical Maintenance

- Check wire connections
 - Wire wear
 - Loose wires
- Blow out coin mechs and motors with compressed air
- Ensure you have the proper amp's for your equipment
 - 3 motors pull 24 amps requiring 30 amp svc
 - 2 motors pull 16 amps requiring 20 amp svc
- Use a licensed Electrician
 - Proper voltage/Length of run/Proper wire gauge

